
















SOLIDWORKS STANDARD TASTATUR GENVEJE

Genvej	Kategori		Kommando
Ctrl + N	File		New
Ctrl + O	File		Open
R	File		Browse Recent Documents
Ctrl + W	File		Close
Ctrl + S	File		Save to PC
Ctrl + Alt + S	File		Save to 3DEXPERIENCE
Ctrl + Shift + S	File		Save As
Ctrl + P	Edit		Print
Ctrl + Z	Edit		Undo
Ctrl + Y	Edit		Redo
Enter	Edit		Repeat Last Command
Ctrl + A	Edit		Select All
Ctrl + X	Edit		Cut
Ctrl + C	Edit		Copy
Ctrl + V	Edit		Paste
Delete	Edit		Delete
Ctrl + B	Edit		Rebuild
Ctrl + Shift + B	Edit		Rebuild All Configurations
Ctrl + Q	Others		Force Rebuild
Ctrl + Shift + Q	Others		Force Rebuild All Configurations
Ctrl + Shift + C	Edit		Copy Appearance
Ctrl + Shift + V	Edit		Paste Appearance











SOLIDWORKS STANDARD TASTATUR GENVEJE

Genvej	Kategori		Kommando
Ctrl + R	View		Redraw
Spacebar	View		Orientation
F	View		Zoom to Fit
Ctrl + Shift + Z	View		Previous View
F3	View		Quick Snaps
F9	View		FeatureManager Tree Area
F10	View		Toolbars
Ctrl + F1	View		Task Pane
F11	View		Full Screen
G	Tools		Magnified Selection
T	Tools		Select over Geometry
Ctrl + A	Tools		Select All
L	Tools		Line
Ctrl + F2	Help		Welcome to SOLIDWORKS
H	Help		Help
W	Help		Commands
I	Help		Files and Models
Ctrl + 1	Others		Front
Ctrl + 2	Others		Back
Ctrl + 3	Others		Left
Ctrl + 4	Others		Right
Ctrl + 5	Others		Top

SOLIDWORKS STANDARD TASTATUR GENVEJE

Genvej	Kategori		Kommando
Ctrl + Next	Others		Next Command Manager Tab
SingleQuote (‘)	Others		Select Annotation View
Ctrl + Prior	Others		Previous Command Manager Tab
Ctrl + Spacebar	Others		View Selector
X	Others		Filter Faces
Y	Others		Accept Edge
Z	Others		Zoom Out
Shift + Z	Others		Zoom In
D	Others		Move Selection Breadcrumbs, Confirmation Corner display to the cursor.
Ctrl + D	Others		Toggle radial dimension display
TAB	Others		Hide the hovered-over Component/Body
Shift + TAB	Others		Show the hovered-over Component/Body
Ctrl + Shift + TAB	Others		Show all hidden Components/Bodies
T	Others		Select over Geometry
H	Search		Search SOLIDWORKS Help
W	Search		Search Commands
I	Search		Search Files and Models

SOLIDWORKS STANDARD TASTATUR GENVEJE

Genvej	Kategori		Kommando
Ctrl + Next	Others		Next Command Manager Tab
SingleQuote (‘)	Others		Select Annotation View
Ctrl + Prior	Others		Previous Command Manager Tab
Ctrl + Spacebar	Others		View Selector
X	Others		Filter Faces
Y	Others		Accept Edge
Z	Others		Zoom Out
Shift + Z	Others		Zoom In
D	Others		Move Selection Breadcrumbs, Confirmation Corner display to the cursor.
Ctrl + D	Others		Toggle radial dimension display
TAB	Others		Hide the hovered-over Component/Body
Shift + TAB	Others		Show the hovered-over Component/Body
Ctrl + Shift + TAB	Others		Show all hidden Components/Bodies
T	Others		Select over Geometry
H	Search		Search SOLIDWORKS Help
W	Search		Search Commands
I	Search		Search Files and Models